

T4 Scandisk Procedure from Windows Explorer

If you are already in Windows Explorer follow the procedure below.

From the "Welcome to T4 Main Menu" screen, hit (Ctrl + Alt) + X to get into Windows Explorer and proceed below.

Scandisk procedure:

On the left hand side of the screen, Left click once on "My Computer" (it will now be highlighted in blue).

Right click on "Local Disc C:" on the **right side** of the screen.

From the menu, choose "Properties" and left click once.

Left click on the "Tools" tab from the window that opens up.

Left click on "Check Now".

Left click once on each white box to place a check mark in each box.

Left click on "Start".

Click "Yes" on the message that pops up asking for re-start.

Click on the "X" in the upper right corner of the screen and you should be back to the "Welcome to T4 Main Menu" screen.

Shut down the laptop and start it back up.

When it starts back up it will run scandisk automatically by going through phases so be patient because it might take a little while.

After it gets done, you might have to hit enter so it re-boots, or it will re-boot on its own.